



	Pieces *Брой Kusú * Stück Cantidad * Huk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucăți Колчество * Stыck Ks. * Kosov * Штуk
	2

	Pieces *Брой Kusú * Stück Cantidad * Huk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucăți Колчество * Stыck Ks. * Kosov * Штуk
G16.	12
G17. ST4x30	12
G18.	8
G19. ST4x10	8
G39.	2
G40.	1
G41.	1
G45. ST3.5x30	4
G46.	2
G47. ST4x20	1
G49.	
G50.	
G48. ST4x20	1
G49.	
G50.	

№ * № * № Nr. * № * arv № * Sorszám № * № * Nr. Nr. * Nr. * Nr. Nr. * № * Nr. Č. * Št. * Nr	Article No. * № на частта Čís. artiklu * Artikel-Nr No. de articulo * Artikel-Nr No. d'article Az alkatrész száma Br dijela * Artículo n. Dajies Nr. * Daju Nr. Nr. onderdeel. * Nr części Nr. piesei Номенклатурный номер Artikelnummer * Č. dielu Št. artikla * Nчастини	Pieces *Брой Kusú * Stück Cantidad * Huk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucăți Колчество * Stыck Ks. * Kosov * Штуk
1.1	600-40018-G8-80	1
1.2	600-40018-G9-80	1
2.1	600-40018-G6	1
2.2	600-40018-G7	1
3	600-40018-G-SC-S-80	2
4	600-40000-G14	2
5	100-40018-G15	2
6	600-40000-C20	1+1
7	600-40018-G55	1
8	600-40018-G56	1
9	600-40018-G57	1
10	600-40018-GW1	1
11	600-40018-G-S/H-S	1