



	Pieces* Брой Kusú* Stúck Cantidad * Hulk Quantité* Darabszám Komadi* Pezzi Vienetai * Gab. Stucks* Szt. * Bucăți Колчество *Styck Ks.* Kosov Штук
C14.	16
C15.	8
C16.	8
C17.	8
C21. C22.	1+1
C23.	2
C24.	4

	Pieces* Брой Kusú* Stúck Cantidad * Hulk Quantité* Darabszám Komadi* Pezzi Vienetai * Gab. Stucks* Szt. * Bucăți Колчество *Styck Ks.* Kosov Штук
	2
	Pieces* Брой Kusú* Stúck Cantidad * Hulk Quantité* Darabszám Komadi* Pezzi Vienetai * Gab. Stucks* Szt. * Bucăți Колчество *Styck Ks.* Kosov Штук
C38.	4
C39.	4

№ *№ * ěís. Nr. *№ * arv № * Sorszám № * №Nr* Nr * Nr * Nr. Nr. * № * Nr Č. * St. * Nr	Article No. * Nena частта Čís. artiklu* Artikel-Nr No.de articulo * Artikel nr No. d'article Az alkatrész száma Br dijela* Articolo n. Dales Nr.* Daju Nr. Nr. onderdeel. * №ěízi Nr. piesei Номенклатурный номер Artikelnummer * Č. dielu Št. artikla * Nčástini	Pieces* Брой Kusú* Stúck Cantidad * Hulk Quantité* Darabszám Komadi* Pezzi Vienetai * Gab. Stucks* Szt. * Bucăți Колчество *Styck Ks.* Kosov Штук
1.1.	600-40001-C5-90	1
1.2.	600-40001-C6-90	1
2.1.	600-40000-C7	1
2.2.	600-40000-C8	1
3.	600-40001-C13-90	1
4.	600-40000-C9	1
5.	600-40000-C10	1
6.	600-40000-C18-19-S	2
7.	600-40000-C20	2
8.	600-40000-C28-C34	1
9.	600-40000-C38-C39	1
10.	600-40000C W1	1