



	Pieces * Брой Kusú * Stúck Cantidad * Hulk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucătj Колчество * Stыck Ks. * Kosov * Штук
C25 C26 ST4x30	1+1+4

	Pieces * Брой Kusú * Stúck Cantidad * Hulk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucătj Колчество * Stыck Ks. * Kosov * Штук
	2

	Pieces * Брой Kusú * Stúck Cantidad * Hulk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucătj Колчество * Stыck Ks. * Kosov * Штук
C14.  ST4x30	16
C15. 	8
C16.  ST4x10	8
C17. 	8
C21. 	1+1
C22. 	1+1
C23. 	2
C24. 	4

	Pieces * Брой Kusú * Stúck Cantidad * Hulk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucătj Колчество * Stыck Ks. * Kosov * Штук
C38 	4
C39 	4

№ * № * №ís. Nr. * № * arv № * Sorszám № * № * № * №. Nr. * Nr. * Nr. Nr. * № * Nr Č. * Št. * Nr	Article No. * №на частта Čís. artiklu * Artikel-Nr No. de articulo * Artikel nr No. d'article Az alkatrész száma Br dijela * Articolo n. Dallies Nr. * Daju Nr. Nr. onderdeel. * №ээи Nr. piesei Номенклатурный номер Artikelnummer * Č. dielu Št. artikla * №частини	Pieces * Брой Kusú * Stúck Cantidad * Hulk Quantité * Darabszám Komadi * Pezzi Vienetai * Gab. Stucks * Szt. * Bucătj Колчество * Stыck Ks. * Kosov * Штук
1.1.	600-40002-C1-80	1
1.2.	600-40002-C2-80	1
2.1.	600-40002-C3-80	1
2.2.	600-40002-C4-80	1
3.	600-40002-C11-C12-80	2
4.	600-40000-C9	1
5.	600-40000-C10	1
6.	600-40000-C19C	2
7.	600-40000-C20	1
8.	600-40000-C28-C34	1
9.	600-40000-C38-C39	1
10.	600-40002-C25-26-C14	2
11.	600-40000-CW1	1